



## **RFP-SF-01-0-2016/TB**

Camp Blanding OSF (Canopy Painting & Repairs)

### **Questions & Answers**

Question Due Date Deadline: Thursday, March 24, 2016

Answer Due Date Deadline: Tuesday, April 5, 2016

Q1: Is power washing permitted?

**A1:** Power washing will NOT be permitted as part of the surface preparation. All areas to be painted should be prepared by scraping, sanding, solvents, and dry power tools. The surface should be prepared so that it meets the requirements of the coatings manufacturer.

Q2: What type of paint is required?

**A2:** 1 coat of - Primer should be Sherwin-Williams B58T00101 Macropoxy 920 PrePrime Rust Penetrating Epoxy Transparent. 2 coats of paint should be Sherwin-Williams B58W00610 Macropoxy 646 Fast Cure Epoxy White.

Other manufacturers of equivalent product will be acceptable.

Q3: Is the “turn around area” included in the scope since it is in much better condition?

**A3:** In this area, only a few of the spots where visible rust is occurring should be treated. There are stabilizing connector rods in the rafters where the paint has completely failed and these rods should all be prepped, primed, and painted with same epoxy paint.

#### Other comments:

1. Proposals should include the terms of the warranty after work is completed.
2. All work performed should comply with the appropriate Davis-Bacon Wage Rates.